



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

A-19

RESTORED

Date ~~Recovered~~: 6 SEPTEMBER 2001Corner Description: NW COR - NE FR $\frac{1}{4}$ 2-22-8Corner Recovered by: A. GUERIN & D. WIMMERSITE MAPMaterial Found: NO STONE OR METAL FOUND.References: 1. NAIL SET IN UTILITY POLE2. CONCRETE POST3. IRON POST4. _____5. _____6. _____Condition of Corner: _____

HOLE DUG AT POINT OF FENCE SPLITS, NO STONE FOUND. #6 REBAR SET WITH CAP BY LINE INTERSECTION OF EXISTING FENCES.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.


**Fanning/Howey**

Engineers

Civil Engineering Division
Surveyors Consultants

PH. 765/664-3690

FAX 765/664-6937



Jorge E. Camacho
Land Surveyor No. SO198