



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 8 DEC. 1993Corner Description: SW COR - SW 1/4 3-22-6Corner Recovered by: A. GUERIN & D. WHIMMERSITE MAPMaterial Found: BRASS ROD

- References:
1. NAIL SET IN UTILITY POLE
 2. CONCRETE R/W MARKER
 3. HOUSE FOUNDATION
 4. _____
 5. _____
 6. _____

Condition of Corner: _____

FOUND 9 Nov. 1999

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # 50198

