




OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 12 AUGUST 1988Corner Description: SW COR. - SW 1/4 1-22-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: STONE 0.8' COVER

- References:
1. CONCRETE POST
 2. CONCRETE POST
 3. BOTTLE CAP IN PUR. POLE
 4. IRON FENCE POST
 5. POWER POLE
 6. _____

Condition of Corner: EXCELLENTCROSS-CUT MADE ON STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Jorge E. Camacho
Land Surveyor # 50198



X