



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

RESTORED:

Date Recovered: 16 JULY 1996

A-21

Corner Description: NW COR - NW FR 1/4 1-22-8Corner Recovered by: A. GUERIN & D. WIMMERMaterial Found: NO POINT FOUND.

- References:
1. STONE FOUND AT SW COR - NW FR 1/4
 2. STONE & FOUND AT SW COR - NW 1/4 - NW FR 1/4
 3. IRON POST
 4. CONCRETE POSTS
 5. AXLE SET AT SW COR - SW 1/4 36-23-8
 6. _____

Condition of Corner: _____

#6 REBAR SET WITH PLASTIC CAP AS PER SURVEY DONE
JUNE 1899.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

