



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 9 MARCH 1995

B-21

Corner Description: SW COR - NW 1/4 - NW 1/4 1-22-8Corner Recovered by: ALAN GUERIN - DON WIMMERMaterial Found: BLUE GRANITE 1.3 BURY

- References:
1. NAIL SET IN WOOD POST
 2. NAIL SET IN UTILITY POLE GR10714
 3. CORNER OF BLOCK BUILDING
 4. #6 REBAR SET
 5. IRON POST
 6.

Condition of Corner: EXCELLANT

#6 REBAR SET WITH PLASTIC CAP OVER STONE.
 SMALL PK NAILS SET AT 5.0 FEET WEST, SE & NE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

Jorge E. Camacho
 Land Surveyor # S0198

