



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: JULY 1993Corner Description: SE COR NE 1/4-NE FR 1/4 1-22-8Corner Recovered by: GRANT CO. SURVEYORS OFFICEREFERENCED BY: A. GUERIN - D. WHITNERMaterial Found: STONE 0.2' COVER

- References:
1. BOTTLE CAP SET IN UTILITY POLE
 2. RAIL POST
 3. _____
 4. _____
 5. _____
 6. _____

Condition of Corner: EXCELLENT

PK NAIL SET AT SURFACE. SMALL PK NAILS SET AT 3.0 FEET EAST, WEST AND SOUTH.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

Jorge E. Camacho
 Land Surveyor # S0198

