



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 13 JULY 93Corner Description: SW COR-NE FR 1/4 1-22-8Corner Recovered by: A. GUERIN - D. WILKINERMaterial Found: GRANITE STONE 1.1' COVER

- References:
1. #6 REBAR SET AT PAVEMENT EDGE
 2. RAIL POST
 3. IRON POST
 4. _____
 5. _____
 6. _____

Condition of Corner: EXCELLENT

FOUND CHISELED CROSS ON STONE. SET #6 REBAR WITH PLASTIC CAP OVER STONE. SET SMALL PK NAILS AT 5.0 FEET NW, SW AND EAST OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198

