



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

E-23

Date Recovered: 13 APRIL 2000Corner Description: SE COR - SW 1/4 1-22-8Corner Recovered by: A. GUERIN, D. WIMMERMaterial Found: GRANITE STONE 0.8' COVER

- References:
1. 46 REBAR SET
 2. NAIL SET IN UTILITY POLE
 3. NAIL SET IN WOOD POST
 4.
 5.
 6.

Condition of Corner: EXCELLENT

BOAT SPIKE SET W/CAP OVER STONE.

SMALL PK NAILS SET AT 5.0' SOUTH, NW & NE.

SMALL PK SET AT SURFACE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Fanning/Howey
Civil Engineering Division
Engineers Surveyors Consultants

PH. 765/664-3690

FAX 765/664-6937

Jorge E. Camacho
Land Surveyor # S0198

