



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 12 APRIL 1991Corner Description: NW COR - NE $\frac{1}{4}$ - SE $\frac{1}{4}$ S-22-8Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: GRANITE STONE 1.1' COVER

- References:
1. #4 REBAR SET ON SHOULDER
 2. BOTTLE CAP SET IN WOOD POST
 3. BOTTLE CAP SET IN PWR. POLE GRID 5-55
 4. BOTTLE CAP SET IN UTILITY POLE
 5. _____
 6. _____

Condition of Corner: EXCELLENTDRILL HOLE MADE IN STONE, RAILROAD BOLT SET.SMALL PK NAILS SET 5.0' EAST, NW & SW

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered ~~OR~~ Restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # 80198

REGISTERED
NO. 80198
STATE OF INDIANA
SURVEYOR