



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA C-1Date Recovered: JULY 1993Corner Description: NW COR - SW 1/4 6-22-9Corner Recovered by: GRANT COUNTY SURVEYORS OFFICEMaterial Found: STONE 0.3 COVER

References:

1. #6 REBAR SET
2. CONCRETE POST
3. _____
4. _____
5. _____
6. _____

Condition of Corner: EXCELLENT

PK NAIL SET AT SURFACE. PK NAILS SET AT 5.0 FEET NORTH, SOUTH AND EAST.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

JORGE E. CAMACHO
REGISTERED
NO. 50198
STATE OF INDIANA
Jorge E. Camacho
Land Surveyor S.J. 80198