


OFFICE OF THE GRANT COUNTY, INDIANA SURVEYOR ** CORNERSTONE RECORD BOOK **


DATE: December 29, 1989

CORNER LOCATED: North $\frac{1}{2}$ Corner Section 2, Twp 23N, R 6E

SITE MAP



DETAIL MAP



CERTIFICATION:

I, the undersigned
a Land Surveyor registered in the State
of Indiana under IC 25-31, do hereby
Certify that I have recovered the Corner
hereon shown and described, on the date
shown above and at the order of the
Grant County, Indiana, Surveyor.

Randall D. Miller
Indiana Number 88000

Material: Brass Pin

References: 1) SW Corner House Foundation

2) Power Pole 1/2 mile East Side

3) 6" Dia. Steel Post (Center)

4) Power Pole 1/2 mile East Side

5)

Condition of Corner: good - 6" deep

Backfilled and paving replaced:

Date Checked:

Condition of Corner and References