



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA E-17Date Recovered: 17 AUGUST 1999Corner Description: SW COR-SW 1/4 2-23-6Corner Recovered by: A. GUERIN & D. WIMMERSITE MAPMaterial Found: IRON ROD IN CONCRETE (FLUSH)

- References:
1. CONCRETE R/W MARKER
 2. NAIL SET IN UTILITY POLE
 3. PORETT FOUNDATION
 4. _____
 5. _____
 6. _____

Condition of Corner: GOOD

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # 50198

REGISTERED
NO. 50198
STATE OF
INDIANA