



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

E-19

Date Recovered: 17 SEPT. 1992Corner Description: SW COR - SE 1/4 2-23-6Corner Recovered by: J. NOBLE & GRANT CO. SURVEYOR OFFICE CREW.Material Found: STONE 1.0' BURY

References:

1. PK NAIL SET IN WOOD POST
2. #5 REBAR SET
3. _____
4. _____
5. _____
6. _____

Condition of Corner: EXCELLENTFOUND SPIKE AND PK NAIL OVER STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198

