



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

A-17

Date Recovered: 25 FEB. 1993Corner Description: NE COR - NE 1/4 3-23-6Corner Recovered by: A. GUERIN & D. WIMMERMaterial Found: IRON ROD IN CONCRETE

- References:
1. NAIL SET IN UTILITY POLE
 2. #6 REBAR SET
 3. CONCRETE R/W MARKER
 4. IRON SIGN POST
 5.
 6.

Condition of Corner:

IRON ROD TAKEN OUT DURING REPAVING OF S.R. #13.
MAG NAIL SET 2 DEC. 1999.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

Jorge E. Camacho
 Land Surveyor # 50198

