

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

Corner Recovered by: ALAN GUERIN & DON WINTER

Hand-drawn map showing a central intersection with four roads:


- 900 West** (top road)
- Co. Rd.** (bottom road)
- GR 6746** (left road)
- Unlabeled road (right road)

Distances and bearings from the intersection to four points:

- Point 1**: 26.88' distance, 20.00° bearing from the right road.
- Point 2**: 18.56' distance, 17.54° bearing from the bottom-right road.
- Point 3**: 17.54' distance, 23.34° bearing from the bottom-left road.
- Point 4**: 26.88' distance, 20.00° bearing from the top-left road.

A small square symbol is located on the left road near Point 3.

References:

1. #6 REBAR SET
2. WPA IRON PIPE FOUND
3. NAIL SET IN UTILITY POLE
4. 
5. 
6. 

PK NAIL SET AT SURFACE. SMALL PK NAILS SET AT 5.0 FEET
EAST, NW & SW OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198

