



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

C-17

Date Recovered: 2 JUNE 1994Corner Description: SE COR - NE 1/4 3-23-6Corner Recovered by: A. GUERIN & D. WITMERSITE MAPMaterial Found: BOAT SPIKE

- References:
1. BACK SIDE OF CONCRETE R/W MARKER
 2. DRILL HOLE FOUND IN CONCRETE HEADWALL
 3. NAIL SET IN UTILITY POLE
 4. _____
 5. _____
 6. _____

Condition of Corner: _____

MAG NAIL SET AT SURFACE 17 AUGUST 1999.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

