



OFFICE OF THE GRANT COUNTY SURVEYOR, MYARION, INDIANA

J-15

Date Recovered: 17 AUG. 1999Corner Description: SE COR - SW 1/4 10-23-6Corner Recovered by: A. GUERIN, D. WIMMERMaterial Found: GRANITE STONE 0.4' COVER

- References:
1. NAIL SET IN UTILITY POLE GR67105
  2. #6 REBAR SET
  3. NAIL SET IN WOOD POST
  4. \_\_\_\_\_
  5. \_\_\_\_\_
  6. \_\_\_\_\_

Condition of Corner: EXCELLENTFOUND DRILL HOLE IN STONE. SET #6 REBAR W/CAP.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or re-established the Corner hereon shown and described.

CAMACHO & NOBLE, INC.  
408 SOUTH MAIN STREET  
P.O. BOX 36  
JONESBORO, INDIANA 46938

