L-25


CORNERSTONE RECORD BOOK

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

Date Recovered: 22 MAY 1989

Corner Description: NE COR. - SE ¼ 13-23-6

Corner Recovered by: A. GUERIN - D. WIMMER



Material Found: BLUE GRANITE STONE 1.2' COVER

References:
1. BOTTLE CAP IN PWR. POLE GR80162
2. BOTTLE CAP IN PWR. POLE GR80161
3. BOTTLE CAP IN WOOD POST
4.
5.
6.

Condition of Corner: EXCELLENT

MADE DRILL HOLE ON STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registerd in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

JORGE E. CAMACHO REGISTERED NO. SO198 STATE OF INDIANA LAND SURVEYOR

Jorge E. Camacho
Land Surveyor # SO198