



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 22 MAY 1989Corner Description: SE COR. - SE $\frac{1}{4}$ 13-23-6Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: LIMESTONE 1.2' COVER

- References:
1. FOUNDATION
 2. DRILL HOLE IN SECOND STEP.
 3. CENTER OF STONE SIGN
 4. BOTTLE CAP IN PWR. POLE GR80146
 5. BOTTLE CAP IN SAWED OFF UTILITY POLE
 6.

Condition of Corner: EXCELLENT

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Jorge E. Camacho
Land Surveyor # 50198

