



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA J-19Date Recovered: 5 APRIL 1999Corner Description: NE COR - NW 1/4 14-23-6Corner Recovered by: A. GUERIN, D. WIMMERMaterial Found: GRANITE STONE 0.8' COVER

- References:
1. W.P.A. IRON ROD FOUND
 2. NAIL SET IN WOOD POST
 3. #6 REBAR SET
 4. CONCRETE POST
 5. NAIL SET IN UTILITY POLE
 6. _____

Condition of Corner: EXCELLENT
#6 REBAR SET W/CAP OVER STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NORRIS
408 SOUTH MAIN
P.O. BOX 10
JONESBORO, INDIANA 46948

Jorge E. Camacho
Land Surveyor # 80198

