



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 13 JAN. 1988Corner Description: SW COR. - SE $\frac{1}{4}$ 14-23-6Corner Recovered by: A. GUERIN - P. HAYNESMaterial Found: STONE 1.1' COVER

References: 1. CONCRETE POST

2. IRON PIPE SET

3. IRON PIPE SET

4. _____

5. _____

6. _____

Condition of Corner: EXCELLENT

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Jorge E. Camacho

Jorge E. Camacho
Land Surveyor # 30198

REGISTERED
NO. 30198
STATE OF
INDIANA
LAND SURVEYOR