



Date Recovered: 5 APRIL 1993

Corner Description: SW COR - SE 1/4, SE 1/4 14-23-6

Corner Recovered by: A. GUERIN - D. WIMMER



Material Found: GRANITE STONE 0.1 BURY

References: 1. BOTTLE CAP SET IN WOOD POST

2. #6 REBAR SET

3. CORNER OF BRICK HOUSE

4. _____

5. _____

6. _____

Condition of Corner: EXCELLENT

SMALL PK NAIL SET AT SURFACE. SMALL PK NAILS SET AT 5.0 FEET;
NW, NE AND SOUTH OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho.....
Land Surveyor # 80198

AEC