



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 13 JAN 1988Corner Description: SE COR. - SE $\frac{1}{4}$ 14-23-6Corner Recovered by: A. GUERIN - P. HAYNESMaterial Found: BLUE GRANITE STONE 1.6' COVER

References: 1. NAIL IN WOOD POST

2. NAIL IN PUR. POLE

3. _____

4. _____

5. _____

6. _____

Condition of Corner: EXCELLENT

FOUND CAP STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Jorge E. Camacho
Land Surveyor # 80198

