J-13


CORNERSTONE RECORD BOOK

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA


Date Recovered: 26 JUNE 1997

Corner Description: NE COR-NE¼ 16-23-6

Corner Recovered by: A. GUERIN - D. WIMMER



SITE MAP



Material Found: GRANITE STONE 0.7' COVER

References:
1. #5 REBAR SET
2. NAIL SET IN WOOD POST
3. NAIL SET IN UTILITY POLE
4.
5.
6.

Condition of Corner: EXCELLENT

1/2" REBAR FOUND 0.7' WEST - 0.8' SOUTH (REMOVED)

SPIKE SET WITH CAP OVER STONE.

SMALL PK NAILS SET AT 5.0' WEST, NORTHEAST & SOUTHEAST

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

JORGE E. CAMACHO
REGISTERED
NO. S0198
STATE OF
INDIANA
LAND SURVEYOR

Jorge E. Camacho
Land Surveyor # S0198