



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 26 JUNE 1997Corner Description: NE COR. SE 1/4 16-23-6Corner Recovered by: A. GUERIN & D. WITMERMaterial Found: GRANITE STONE 1.6 COVER

References:

1. #5 REBAR SET
2. NAIL SET IN UTILITY POLE
3. NAIL SET IN WOOD POST
4.
5.
6.


Condition of Corner: EXCELLENT

#6 REBAR SET WITH CAP OVER STONE.

SMALL PK NAILS SET AT 5.0' WEST, NORTHEAST & SOUTHEAST.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938



Jorge E. Camacho
Land Surveyor # S0198