
CORNERSTONE RECORD BOOK

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA N-11

Date Recovered: 2 MAY 1991

Corner Description: NW COR - NE 1/4 21-23-6

Corner Recovered by: A. GUERIN - D. WILHELM



Material Found: GRANITE STONE 1.0' COVER

References:
1. BOTTLE CAP SET IN PWR. POLE GR7892
2. BOTTLE CAP SET IN PWR. POLE GR7882
3. WPA IRON PIPE FOUND
4. BOTTLE CAP SET IN WOOD POST
5. #5 REBAR SET
6. ———

Condition of Corner: EXCELLENT

LARGE BOLT SET OVER STONE.
PK NAIL FOUND 1.8' SOUTH & 1.2' WEST.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registerd in the State of Indiana under IC 25-31, do hereby Certify that I have recovered OR Restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

JORGE E. CAMACHO REGISTERED NO. S0198 STATE OF INDIANA LAND SURVEYOR

Jorge E. Camacho
Land Surveyor # S0198