N-13


CORNERSTONE RECORD BOOK

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA


Date Recovered: 2 MAY 1991

Corner Description: NE COR. NE ¼ 21-23-6

Corner Recovered by: A. GUERIN - D. WILMER



SITE MAP



Material Found: GRANITE STONE 0.5' COVER

References:
1. BOTTLE CAP SET IN POWER POLE GR7837
2. CONCRETE POST
3. WELL CASING
4. BOTTLE CAP SET IN WOOD POST
5. ———
6. ———

Condition of Corner: EXCELLENT

DRILL HOLE FOUND ON STONE. LARGE NAIL SET.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registerd in the State of Indiana under IC 25-31, do hereby Certify that I have recovered OR Restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

JORGE E. CAMACHO REGISTERED NO. SO198 STATE OF INDIANA LAND SURVEYOR

Jorge E. Camacho
Land Surveyor # SO198