



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

P-17

Date Recovered: 16 JUNE 1987Corner Description: NE COR - SE 1/4 22-23-6Corner Recovered by: A. GUERIN & C. HAYNESMaterial Found: BOLT FOUND


- References:
1. DRILL HOLE FOUND IN HEADWALL
 2. NAIL SET IN UTILITY POLE
 3. CONCRETE R/W MARKER
 4. DRILL HOLE MADE IN HEADWALL
 5. _____
 6. _____

Condition of Corner: _____

MAG NAIL SET 9 NOV. 1999

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 26
 JONESBORO, INDIANA 46938



Jorge E. Camacho
 Land Surveyor # 50198

V