



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 24 APRIL 1995Corner Description: NE COR-NE 1/4 33-23-6Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: GRANITE STONE 1.5' COVER

- References:
1. #6 REBAR SET
 2. NAIL SET IN UTILITY POLE GR8937
 3. CONCRETE POST
 4. NAIL SET IN WOOD POST
 5.
 6.

Condition of Corner: EXCELLENT

FOUND IRON ROD OVER STONE. REPLACED WITH #6 REBAR WITH PLASTIC CAP. SMALL PK NAILS SET AT 5.0' WEST, NE, SE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or re-established the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198

