



Z-17

Corner Recovered by: A. GUERIN - D. WIMMER



Material Found: STONE 1.5' COVER

References:

1. CONCRETE POST
2. NAIL SET IN UTILITY POLE
3. CONCRETE HEADWALL
4. GUARDRAIL POST
5. NAIL SET IN WOOD post
6. _____

Condition of Corner: EXCELLENT

IRON PIPE FOUND OVER STONE. REPLACED WITH #6 REBAR WITH PLASTIC CAP. SMALL PK NAILS SET AT 5.0' FEET NW, SW AND EAST OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or Restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

covered or restored the

REGISTERED
NO. 50198
STATE OF
INDIANA

Jorge E. Camacho
Land Surveyor #RS0198