



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

Z-19

Date Recovered: 15 NOVEMBER 1995Corner Description: SE COR - SW 1/4 35-23-6Corner Recovered by: A. GUERIN & D. WIMMERMaterial Found: SANDSTONE 1.1' COVER

- References:
1. CONCRETE POST
 2. #6 REBAR SET ON PAVEMENT EDGE
 3. NAIL SET IN UTILITY POLE
 4. _____
 5. _____
 6. _____

Condition of Corner: GOODFOUND OLD WOOD HUB OVER STONE.#6 REBAR SET WITH CAP.SMALL PK'S SET AT 5.0' FT. NORTH, SE & SW.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
400 SOUTH MAIN STREET
P.O. BOX 26
JONESBORO, INDIANA 46933

Jorge E. Camacho
Land Surveyor # S0198

