



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

RESTORED

Date ~~Recovered~~: 24 APRIL 1992

Corner Description: NW COR - NW 1/4 36-23-6

Corner Recovered by: A. GUERIN - D. WIMMER



Material Found: NO STONE FOUND.


- References:
- CORNER OF BRICK PORCH
 - BOTTLE CAP SET IN WOOD POST
 - CONCRETE POST
 - BOTTLE CAP SET IN PWR. POLE GR9075
 - _____
 - _____

Condition of Corner: _____

#6 REBAR SET. (SEE REVERSE SIDE)


I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938



Jorge E. Camacho
Land Surveyor # S0198

AEG



NW COR - NW $\frac{1}{4}$
#6 REBAR SET

SW COR - NW $\frac{1}{4}$ - NW $\frac{1}{4}$
STONE FOUND

SW COR - NW $\frac{1}{4}$
IRON PIPE FOUND