Z-23

CORNERSTONE RECORD BOOK


OFFICE OF THE GRANT COUNTY SURVEYOR. MARION, INDIANA

Date Recovered: OCTOBER 14, 1985


Corner Description: SW COR SE 1/4 36-23-6

Corner Recovered by: V. CAMACHO - J. TODD - R. WILKES - B. RIGNEY

R-6-E



SITE MAP



CERTIFICATION:

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby certify that I have recovered the corner hereon shown and described.

Jorge E. Camacho

Jorge E. Camacho. R.L.S.
Indiana SO 198

JORGE E. CAMACHO
REGISTERED
NO. SO198
STATE OF
INDIANA
LAND SURVEYOR

Material Found: SANDSTONE - + MARK - PICTURE TAKEN

References:

1. PK NAIL IN POW. POLE GR 101.77
2. PK NAIL IN POW. POLE
3. PK NAIL IN CONC. SLAB
4. PK NAIL IN POW. POLE GR 101.76
5. TRACK SPIKE 5.0± SOUTH OF ℄ IMP.
6. TRACK SPIKE 5.5± SOUTH OF ℄ IMP.
7. TRACK SPIKE 4.1± NORTH OF ℄ IMP.
8. TRACK SPIKE 3.4± NORTH OF ℄ IMP.

Condition of corner: GOOD - STONE 1/2 INCH COVER - BLACTOP PAVEMENT