
CORNERSTONE RECORD BOOK

OFFICE OF THE GRANT COUNTY SURVEYOR. MARION, INDIANA


Date Recovered: OCTOBER 14, 1985

Corner Description: SE COR SE 1/4 36-23-6

Corner Recovered by: J.CAMACHO-J.TODD-R.WILKES-B.RIGNEY



SITE MAP



CERTIFICATION:

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby certify that I have recovered the corner hereon shown and described.

Jorge E. Camacho

Jorge E. Camacho. R.L.S
Indiana SO 198

JORGE E. CAMACHO
REGISTERED
NO. SO198
STATE OF
INDIANA
LAND SURVEYOR

Material Found: GRANITE STONE DRILL HOLE - PICTURE TAKEN

References:

1. PK NAIL P.P. GR 101-63
2. PK NAIL FEN. COR. POST (ROUND)
3. PK NAIL MAPLE TREE
4. PK NAIL MAPLE TREE
5. PK NAIL IN PVMT 6.2± EAST OF ℄ IMP.
6. PK NAIL IN PVMT 5.3± WEST OF ℄ IMP.
7. PK NAIL IN PVMT 7.0± WEST OF ℄ IMP.
8. PK NAIL IN PVMT 5.3± EAST OF ℄ IMP.

Condition of corner: GOOD - STONE EXPOSED - BLACTOP PAVEMENT