



(NOT FOR PAYMENT)

Date Recovered: 23 APRIL 1992

Corner Description: SW COR- SE 1/4 1-23-7

Corner Recovered by: A. GUERIN. D. WIMMER



(NOT FOR PAYMENT)

Material Found: IRON PIN OVER GRANITE STONE 1.0' COVER


- References:
1. WITNESS POST OF THE OFFICE OF THE GRANT COUNTY SURVEYOR.
 2. CONCRETE POST
 3. IRON POST
 4. BOTTLE CAP SET IN PWR. POLE
 5. BOTTLE CAP SET IN WOOD POST
 6. BROKE OFF IRON POST

Condition of Corner: EXCELLENT

CORNER WAS RECOVERED BY THE OFFICE OF THE GRANT CO. SURVEYOR BUT RECORD WAS LOST.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938



Jorge E. Camacho
Land Surveyor # S0198