
E-24

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA


Date Recovered: 23 APRIL 1992

Corner Description: SE COR. SW 1/4 - SE 1/4 1-23-7

Corner Recovered by: A. GUERIN - D. WIMMER



SITE MAP



Material Found: GRANITIE STONE 0.7' COVER

References:
1. BOTTLE CAP SET IN PWR. POLE GR71170
2. #6 REBAR SET AT EDGE OF PAVEMENT
3. IRON POST BROKE OFF AT GROUND
4. ———
5. ———
6. ———

Condition of Corner: EXCELLENT

TRACK SPIKE SET AT SURFACE.
SMALL PK NAILS SET AT 5.0 FEET NW, NE & S

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

JORGE E. CAMACHO REGISTERED NO. S0198 STATE OF INDIANA LAND SURVEYOR

Jorge E. Camacho
Land Surveyor # S0198