



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

C-21

Date Recovered: 9 AUGUST 1995Corner Description: SE COR - NE 1/4 2-23-7Corner Recovered by: A. GUERIN & D. WHITMERMaterial Found: GRANITE STONE 0.1' COVER

- References:
1. #6 REBAR SET
 2. NAIL SET IN WOOD POST
 3.
 4.
 5.
 6.

Condition of Corner: EXCELLENTPK NAIL SET AT SURFACE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered and restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

