



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

E -

Date Recovered: SEPT. 1995


Corner Description: SW Cor-SW FR 1/4 6-23-7

Corner Recovered by: A. GUERIN & D. WIMMER, J. NOBLE
GRANT CO. HIGHWAY DEPT. 151



Material Found: STONE FOUND (REMOVED BY BACKHOE)

References:

1. #6 REBAR SET
2. NAIL SET IN UTILITY POLE
3. NAIL SET IN WOOD POLE WITH TEL. BOX
4. 
5. 
6. 

Condition of Corner: _____
#6 REBAR SET WITH PLASTIC CAP IN PLACE OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408. SOUTH MAIN STREET
P.O. BOX 36
DONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198