



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA E-3Date Recovered: SEPT. 1995Corner Description: SE COR-SW 1/4 6-23-7Corner Recovered by: A. GUERIN & D. WIMMERMaterial Found: GRANITE STONE 0.8' COVER

- References:
1. #6 REBAR SET
 2. NAIL SET IN UTILITY POLE
 3.
 4.
 5.
 6.

Condition of Corner: EXCELLENT

HARROW TOOTH WITH PLASTIC CAP SET OVER STONE.
SMALL PK NAILS SET AT 5.0' NORTH, S.E. AND S.W. OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

Jorge E. Camacho
 Land Surveyor # S0198