CORNERSTONE RECORD BOOK


OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA


G-11

Date Recovered: 17 AUG. 1994

Corner Description: NW COR - SE 1/4 9-23-7

Corner Recovered by: A. GUERIN & D. WIMMER





Material Found: GRANITE STONE 0.3' COVER

References:
1. NAIL SET IN WOOD POST
2. #6 REBAR SET
3. #6 REBAR SET IN CENTER OF CONC. BASE FOR POST
4.
5.
6.

Condition of Corner: EXCELLENT

MADE CROSS ON STONE. SET #6 REBAR ON SOUTH SIDE OF STONE AS A WITNESS. SET PK NAIL ON SURFACE. SET SMALL PK NAILS AT 5.0 FEET EAST, N.W. AND S.W. OF STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

JORGE E. CAMACHO REGISTERED NO. S0198 STATE OF INDIANA LAND SURVEYOR

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198