	3-20-84				
CORNER LOCA	TED: SE COR	NER SEC. 9 TW	). 23 N. R.	7 E.	
SITE MAP			DETAIL 1		
			15 MAPLE	ka M.K.	
			1/22 { O		CON. POST
	300 W		~		IN CENT
	4 8		700S.	8.49	
	7			136	
			\	27.46 Z	
	700 S.	:	·×-x-Ţ	8/	/
	<b>*</b>			P.K.	
CERTIFICATION To the under	ON: rsigned Robert	A Repodiat	A STATE OF THE PARTY OF THE PAR	ERT A. BENDING	
a Land Surve	eyor registered	in the State	408	GISTER	
of Indiana	under IC 25-31,	do hereby			
	: I have recove n and described		• (	No. 9230	
shown above	and at the ord	er of the	15	M. OF J. D. J.	
_	, Indiana, Sur	veyor.		OSUBVEYOUR	
Celush (	Benedict			The state of the s	
Robert A. Be Indiana Numb	enedict, R.L.S.		•		
	<u> </u>		<del></del>		
Material:			<del></del> -		
References:	1) 15" MAPI	LE TREE PK NAI	L S. 54° E	55.55'	··
	2) CONCRETE	POST TRACK SP	IKE IN CENTI	ER S. 49° W.	28.0
		•			
	3) WOOD CORN	VER POST N.	46°, E.	27.3'	
	/ \		· · · · · · · · · · · · · · · · · · ·		
	4)				
	4)				
	5)				
Condition of	5)	BLUE GRANTT	STONE 16	U IMDED DAVEME	NTT
•	5) Corner: GOOD		E STONE 16	" UNDER PAVEME	NT
•	5)		E STONE 16	" UNDER PAVEME	NT
Condition of Backfilled a	5) Corner: GOOD nd paving repla	aced:		" UNDER PAVEME  Corner and Ref	
Backfilled a	5) Corner: GOOD nd paving repla	aced:			
Backfilled a	5) Corner: GOOD nd paving repla	aced:			