



CORNERSTONE RECORD BOOK

2-21

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 18 NOV. 1993Corner Description: NW Cor - SW 1/4 13-23-7Corner Recovered by: A. GUERIN & D. WIMMERMaterial Found: GRANITE STONE 0.4' COVER

- References:
1. IRON PIPE FOUND
 2. NAIL SET IN WOOD POST
 3. PORCH FOUNDATION
 4. #6 REBAR SET
 5. _____
 6. _____

Condition of Corner: EXCELLENT

IRON PIPE FOUND OVER STONE, REPLACED WITH #6 REBAR WITH PLASTIC CAP.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.



CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198



CORNERSTONE RECORD BOOK

2-21

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 18 NOV. 1993Corner Description: NW Cor - SW 1/4 13-23-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: GRANITE STONE 0.4' COVER

- References:
1. IRON PIPE FOUND
 2. NAIL SET IN WOOD POST
 3. PORCH FOUNDATION
 4. #6 REBAR SET
 5. _____
 6. _____

Condition of Corner: EXCELLENT

IRON PIPE FOUND OVER STONE, REPLACED WITH #6 REBAR WITH PLASTIC CAP.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

