



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 17 MAY 1989Corner Description: SW COR-NE $\frac{1}{4}$ 15-23-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: GRANITE STONE

References: 1. 6" IRON POST

2. 6" IRON POST

3. _____

4. _____

5. _____

6. _____

Condition of Corner: EXCELLENT

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Jorge E. Camacho
Land Surveyor

REGISTERED
NO. 80198
STATE OF INDIANA
LAND SURVEYOR