

CORNERSTONE RECORD BOOK



L-17^r

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

Date Recovered: 17 MAY 1989

Corner Description: SE COR. - NE $\frac{1}{4}$ 15-23-7

Corner Recovered by: A. GUERIN - D. WILMER




Material Found: GRANITE STONE 0.5 COVER

- References:
1. RAIL POST
 2. IRON PIPE FOUND
 3. IRON PIPE SET
 4. BOTTLE CAP IN PWR. POLE GR8168
 5. _____
 6. _____

Condition of Corner: EXCELLENT

1 $\frac{1}{4}$ " IRON PIPE FOUND 0.9' WEST - 0.2' NORTH, REMOVED.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.


 Jorge E. Camacho
 Land Surveyor # 50198
 INDIANA