



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANADate Recovered: 11 AUGUST 1988Corner Description: NE COR. - SE $\frac{1}{4}$ 17-23-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: RED GRANITE STONE 0.4 COVER

- References:
1. BOTTLE CAP IN WOOD POST
 2. BOTTLE CAP IN WOOD POST
 3. BOTTLE CAP IN 36" SYCAMORE
 4. BOTTLE CAP IN PWR. POLE GR803
 5. BROKE OFF ANGLE IRON POST
 6. & 7. CONCRETE HEADWALLS -

Condition of Corner: EXCELLENTCROSS CUT MADE IN STONE,

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

Jorge E. Camacho
 Jorge E. Camacho
 Land Surveyor # S0198