



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA N-7

RESTORED


Date ~~Restored~~: 25 JANUARY 1996Corner Description: SW COR-SE¹/₄ 17-23-7Corner Recovered by: A. GUERIN & D. WHITMERMaterial Found: CORNER TAKEN OUT BY NEW CULVERT.

- References:
1. NAIL SET IN WOOD POST WITH PHONE BOX
 2. NAIL SET IN UTILITY POLE
 3. NEW CONCRETE BOX CULVERT
 4. IRON PIPE FOUND @ SW COR-SW¹/₄ 17-23-7
 5. STONE @ SE COR-SE¹/₄ 17-23-7
 6. _____

Condition of Corner: _____

QUARTER SECTION CORNER SET BY SPLITTING NAIL AND CONCRETE CULVERT. PK NAIL SET AT SURFACE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.



Jorge E. Camacho, SURV.
Land Surveyor # 50198