CORNERSTONE RECORD BOOK


N - 9


OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

Date Recovered: 11 AUGUST 1988

Corner Description: SE COR. - SE 1/4 17-23-7

Corner Recovered by: A. GUERIN - D. WIMMER





Material Found: WHITE GRANITE STONE 1.0' COVER

References:
1. BOTTLE CAP IN SAWED OFF UTILITY POLE
2. IRON POST
3. ANGLE IRON POST
4. BOTTLE CAP IN PWR. POLE GR8013
5.
6.

Condition of Corner: EXCELLENT

CROSS CUT MADE IN STONE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registerd in the State of Indiana under IC 25-31, do hereby Certify that I have recovered of restored the Corner hereon shown and described.

JORGE E. CAMACHO REGISTERED NO. S0198 STATE OF INDIANA LAND SURVEYOR

Jorge E. Camacho
Land Surveyor # S0198