CORNERSTONE RECORD BOOK

N-5

OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

Date Recovered: 19 FEBRUARY 1996

Corner Description: NW COR - NW 1/4 20-23-7

Corner Recovered by: A. GUERIN - D. WIMMER



SITE MAP



Material Found: STONE 1.2' COVER

References:

1. #6 REBAR SET
2. N.E. COR. OF CONCRETE POST
3. NAIL SET IN UTILITY POLE
4. NAIL SET IN WOOD POST
5.
6.

Condition of Corner: EXCELLENT

IRON PIPE FOUND OVER STONE, REPLACED WITH #6 REBAR WITH CAP. SMALL PK NAILS SET AT 5.0' SOUTH, NE & NW OF STONE. SMALL PK SET AT SURFACE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

REGISTERED NO. S0198 STATE OF INDIANA

CAMACHO & NOBLE, INC.
408 SOUTH MAIN STREET
P.O. BOX 36
JONESBORO, INDIANA 46938

Jorge E. Camacho
Land Surveyor # S0198