



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

P-5

Date Recovered: 19 FEBRUARY 1996Corner Description: SW COR - NW 1/4 20-23-7Corner Recovered by: A. GUERIN - D. WIMMERMaterial Found: GRANITE STONE 1.0' COVER

References:

1. NAIL SET IN WOOD POST
2. #6 REBAR SET IN PAVEMENT EDGE
3. _____
4. _____
5. _____
6. _____

Condition of Corner: EXCELLENTTRACK SPIKE WITH PLASTIC CAP SET.SMALL PK NAILS SET AT 5.0' EAST, SW AND NW OF STONE

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 16
 JONESBORO, INDIANA 46938

Jorge E. Camacho
 Land Surveyor # S0198

