



OFFICE OF THE GRANT COUNTY SURVEYOR, MARION, INDIANA

P-9

Date Recovered: 19 FEBRUARY 1996Corner Description: SE COR-NE 1/4 20-23-7Corner Recovered by: A. GUERIN - D. WILKINSONMaterial Found: LIMESTONE 1.0' COVER

- References:
1. CONCRETE POST
 2. #6 REBAR SET AT PAVEMENT EDGE
 3.
 4.
 5.
 6.

Condition of Corner: GOOD

SPIKE FOUND REPLACED WITH #6 REBAR WITH PLASTIC CAP.
 SMALL PK NAILS SET AT 5.0' EAST, SW & NW OF STONE.
 SMALL PK SET AT SURFACE.

I, the undersigned Jorge E. Camacho, a Land Surveyor Registered in the State of Indiana under IC 25-31, do hereby Certify that I have recovered or restored the Corner hereon shown and described.

CAMACHO & NOBLE, INC.
 408 SOUTH MAIN STREET
 P.O. BOX 36
 JONESBORO, INDIANA 46938

Jorge E. Camacho
 Land Surveyor # S0198

